



# OneStor USM

## USM\_ONESTOR\_V5.2\_R2019.20.16

### Release Notes

Version 1.0

Seagate  
Langstone Road  
Havant  
Hampshire  
PO9 1SA  
United Kingdom

**Copyright © Seagate 2024. All Rights Reserved.**

**Security Notice**

This document contains confidential proprietary information. None of the information shall be divulged to persons other than Seagate employees, authorized by the nature of their duties to receive such information, or individuals of organizations authorized by Seagate, in accordance with existing policies concerning the release of company information.

**Seagate Confidential**

---

## Table of Contents

|          |   |           |
|----------|---|-----------|
| <b>1</b> | <b>Introduction.....</b>                      | <b>4</b>  |
| 1.1      | What is GEM USM? .....                        | 4         |
| 1.2      | Scope 4                                       |           |
| 1.3      | Terms and Abbreviations.....                  | 4         |
| <b>2</b> | <b>Version Information .....</b>              | <b>5</b>  |
| 2.1      | GEM Subsystem Firmware .....                  | 5         |
| 2.2      | Controllers.....                              | 5         |
| 2.2.1    | Pimlico - E12EBD .....                        | 5         |
| 2.2.2    | Pimlico - E12EBD - Lattice .....              | 5         |
| 2.2.3    | Gallium .....                                 | 5         |
| 2.2.4    | Indium .....                                  | 5         |
| 2.2.5    | Pleasanton Express.....                       | 6         |
| 2.2.6    | Cobra+ EBOD .....                             | 6         |
| 2.2.7    | Battleship EBOD .....                         | 7         |
| 2.3      | Sideplanes.....                               | 8         |
| 2.3.1    | SP-3584 - Titan 12G Sideplanes .....          | 8         |
| 2.3.2    | SP-3584 - Titan 12G Sideplanes - Lattice..... | 9         |
| 2.3.3    | SP-34106 - Cobra+ Sideplanes .....            | 9         |
| 2.3.4    | SP-34106 - Battleship Sideplanes .....        | 10        |
| 2.4      | Midplanes - OneStor .....                     | 11        |
| 2.4.1    | HB1235.....                                   | 11        |
| 2.4.2    | EB2425 .....                                  | 11        |
| 2.4.3    | HB2435.....                                   | 11        |
| 2.4.4    | SP3212A.....                                  | 11        |
| 2.4.5    | SP3212A - Lattice .....                       | 11        |
| 2.4.6    | SP3224A.....                                  | 11        |
| 2.4.7    | SP3224A - Lattice .....                       | 12        |
| 2.4.8    | SP3584 - Titan 12G.....                       | 12        |
| 2.4.9    | SP3584 - Titan 12G - Lattice .....            | 12        |
| 2.4.10   | SP34106 - Cobra+ .....                        | 12        |
| 2.4.11   | SP34106 - Battleship.....                     | 12        |
| 2.5      | Midplanes - OneStor-XP .....                  | 12        |
| 2.5.1    | XP-PL24P .....                                | 12        |
| 2.6      | PCMs / PSUs .....                             | 13        |
| 2.6.1    | HE580W Gen2 - OneStor .....                   | 13        |
| 2.6.2    | HE764W - OneStor .....                        | 13        |
| 2.6.3    | HE764WDC - OneStor .....                      | 13        |
| 2.6.4    | HE764W_VERC - OneStor.....                    | 13        |
| 2.6.5    | HE764WDC_VERC - OneStor .....                 | 13        |
| 2.6.6    | PT580W - OneStor.....                         | 14        |
| 2.6.7    | PT764W - OneStor.....                         | 14        |
| 2.6.8    | TT2200W - SP3584 .....                        | 14        |
| 2.6.9    | 2200W - SP3584 .....                          | 14        |
| 2.6.10   | 1440W - OneStor-XP .....                      | 14        |
| 2.6.11   | 2000W - SP34106 .....                         | 14        |
| 2.7      | Fan Modules .....                             | 15        |
| 2.7.1    | SP3584 .....                                  | 15        |
| 2.7.2    | XP-PL24P .....                                | 15        |
| <b>3</b> | <b>Firmware Update Procedure .....</b>        | <b>16</b> |
| 3.1      | OneStor .....                                 | 16        |
| 3.1.1    | Enclosure Upgrade Steps.....                  | 16        |
| 3.2      | Cobra+ Update Procedure.....                  | 17        |
| 3.3      | OneStor-XP .....                              | 18        |
| 3.3.1    | BMC.....                                      | 18        |
| 3.3.2    | CPLD.....                                     | 18        |
| 3.3.3    | GEM Components.....                           | 18        |
| <b>4</b> | <b>Change History .....</b>                   | <b>20</b> |

|      |  |    |
|------|--|----|
| 4.1  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.16 ..... | 20 |
| 4.2  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.15 ..... | 21 |
| 4.3  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.14 ..... | 22 |
| 4.4  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.12 ..... | 22 |
| 4.5  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.11 ..... | 22 |
| 4.6  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.10 ..... | 24 |
| 4.7  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.9 .....  | 24 |
| 4.8  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.8 .....  | 24 |
| 4.9  | Issues addressed in USM_ONESTOR_V5.2_R2019.20.7 .....  | 25 |
| 4.10 | Issues addressed in USM_ONESTOR_V5.2_R2019.20.6 .....  | 25 |
| 4.11 | Issues addressed in USM_ONESTOR_V5.2_R2019.20.5 .....  | 25 |
| 4.12 | Issues addressed in USM_ONESTOR_V5.2_R2019.20.4 .....  | 26 |
| 4.13 | Issues addressed in USM_ONESTOR_V5.2_R2019.20.3 .....  | 26 |
| 4.14 | Issues addressed in USM_ONESTOR_V5.2_R2019.20.2 .....  | 26 |

# 1 Introduction

## 1.1 What is GEM USM?

GEM Unified System Management (USM) combines the firmware from the GEM subsystem found in a traditional SBB Canister (GEM FW running on SAS expander, GEM Main CPLD, GEM Power CPLD) with firmware from other enclosure components, such as x86 subsystems (primarily BIOS, BMC and FPGA/CPLD components), to provide a coherent system management solution for a range of OneStor platform solutions.

## 1.2 Scope

This release note covers the USM\_ONESTOR\_V5.2\_R2019.20.16 firmware package for all OneStor enclosures. It contains all required controller level, enclosure level, fan level and PCM/PSU level firmware components.

## 1.3 Terms and Abbreviations

|      |   |
|------|---|
| BBU: | Battery Backup Unit                     |
| GEM: | Generic Enclosure Management (Firmware) |
| PCM: | Power Cooling Module                    |
| PSU: | Power Supply Unit                       |
| SBB  | Storage Bridge Bay                      |
| USM: | Unified System Management               |
| VPD: | Vital Product Data                      |
| WWN: | World Wide Name                         |

## 2 Version Information

This section shows the firmware component versions contained in this package and highlights in yellow the items which have changed since the previous GEM USM package.

### 2.1 GEM Subsystem Firmware

#### 2.2 Controllers

##### 2.2.1 Pimlico - E12EBD

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Bootloader    | 2.01                         |
| Firmware      | 5.2.0.207                    |
| VPD Structure | 0x6                          |
| VPD CRC       | 0x8eb959a1                   |
| Config CRC    | 0x79e10778                   |
| GEM CPLD      | 0x0b.00                      |

##### 2.2.2 Pimlico - E12EBD - Lattice

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Bootloader    | 2.01                         |
| Firmware      | 5.2.0.207                    |
| VPD Structure | 0x6                          |
| VPD CRC       | 0xd5f28e7a                   |
| Config CRC    | 0x79e10778                   |
| GEM CPLD      | 0x20.00                      |

##### 2.2.3 Gallium

| USM Package             | USM_ONESTOR_V5.2_R2019.20.16 |
|-------------------------|------------------------------|
| Bootloader              | 2.01                         |
| Firmware                | 5.2.0.207                    |
| VPD Structure           | 0x06                         |
| VPD CRC                 | 0x4c7d0269                   |
| Gallium NX - Config CRC | 0x3bd5bf50                   |
| Gallium PX - Config CRC | 0xc815102e                   |

##### 2.2.4 Indium

| USM Package | USM_ONESTOR_V5.2_R2019.20.16 |
|-------------|------------------------------|
| Bootloader  | 1.0b                         |

|               |            |
|---------------|------------|
| Firmware      | 5.2.0.207  |
| Indium LX     |            |
| VPD Structure | 0x6        |
| VPD CRC       | 0x621d3cf  |
| Config CRC    | 0x96f85db1 |
| Indium NX     |            |
| VPD Structure | 0x6        |
| VPD CRC       | 0x59af3f91 |
| Config CRC    | 0xf75c88d3 |

## 2.2.5 Pleasanton Express

| USM Package           | USM_ONESTOR_V5.2_R2019.20.16 |
|-----------------------|------------------------------|
| GEM Firmware          | 5.2.0.207                    |
| EPM Firmware          | 5.2.0.207                    |
| VPD Structure         | 0x08                         |
| VPD CRC               | 0x10c71276                   |
| Eth Switch EEPROM CRC | 0x89de95af                   |
| GEM CPLD              | 16.00.0                      |
| BMC Boot              | 0.00.0000                    |
| BMC Root              | 0.00.0000                    |
| Main CPLD             | 0.00.0000000014              |

## 2.2.6 Cobra+ EBOD

| USM Package        | USM_ONESTOR_V5.2_R2019.20.16 |
|--------------------|------------------------------|
| Bootloader         | 1.0b                         |
| Firmware           | 5.2.0.207                    |
| MAG FPGA           | 25.00                        |
| Primary Expander   |                              |
| Flash Config       | 0x87208397                   |
| VPD Structure      | 0x01                         |
| VPD CRC            | 0x51e5446e                   |
| Secondary Expander |                              |
| Flash Config       | 0xd519302b                   |
| VPD Structure      | 0x01                         |
| VPD CRC            | 0xc65bae89                   |

## 2.2.7 Battleship EBOD

| USM Package           | USM_ONESTOR_V5.2_R2019.20.16 |
|-----------------------|------------------------------|
| Package Version       | 0x1019                       |
| Bootloader            | 1.0b                         |
| Firmware              | 5.2.0.207                    |
| MAG FPGA              | 25.00                        |
| 10 HDD Baseplane CPLD | 04.00                        |
| Primary Expander      |                              |
| Flash Config          | 0x12b35913                   |
| VPD Structure         | 0x1.0                        |
| VPD CRC               | 0xabd3798e                   |
| Secondary Expander    |                              |
| Flash Config          | 0x0550261a                   |
| VPD Structure         | 0x1.0                        |
| VPD CRC               | 0x37bcc576                   |

## 2.3 Sideplanes

### 2.3.1 SP-3584 - Titan 12G Sideplanes

| USM Package                 | USM_ONESTOR_V5.2_R2019.20.16 |
|-----------------------------|------------------------------|
| Bootloader                  | 2.01                         |
| Firmware                    | 5.2.0.207                    |
| Left Hand CPLD              | 0x07                         |
| Right Hand CPLD             | 0x07                         |
| Left Hand 36 Port Expander  |                              |
| VPD Structure               | 0x07                         |
| VPD CRC                     | 0xbb47c664                   |
| Config CRC                  | 0x61a3e81a                   |
| Left Hand 24 Port Expander  |                              |
| VPD Structure               | 0x07                         |
| VPD CRC                     | 0x60787376                   |
| Config CRC                  | 0xfe7bc727                   |
| Right Hand 36 Port Expander |                              |
| VPD Structure               | 0x07                         |
| VPD CRC                     | 0x6f96875e                   |
| Config CRC                  | 0xc589b747                   |
| Right Hand 24 Port Expander |                              |
| VPD Structure               | 0x07                         |
| VPD CRC                     | 0x2035d972                   |
| Config CRC                  | 0xbc4ca602                   |

### 2.3.2 SP-3584 - Titan 12G Sideplanes - Lattice

| USM Package                 | USM_ONESTOR_V5.2_R2019.20.16 |
|-----------------------------|------------------------------|
| Bootloader                  | 2.01                         |
| Firmware                    | 5.2.0.207                    |
| Left Hand CPLD              | 0x22                         |
| Right Hand CPLD             | 0x22                         |
| Left Hand 36 Port Expander  |                              |
| VPD Structure               | 0x07                         |
| VPD CRC                     | 0xeed8a4c3                   |
| Config CRC                  | 0x61a3e81a                   |
| Left Hand 24 Port Expander  |                              |
| VPD Structure               | 0x07                         |
| VPD CRC                     | 0xb6de4030                   |
| Config CRC                  | 0xfe7bc727                   |
| Right Hand 36 Port Expander |                              |
| VPD Structure               | 0x07                         |
| VPD CRC                     | 0xf762f21d                   |
| Config CRC                  | 0xc589b747                   |
| Right Hand 24 Port Expander |                              |
| VPD Structure               | 0x07                         |
| VPD CRC                     | 0x3775e8c5                   |
| Config CRC                  | 0xbc4ca602                   |

### 2.3.3 SP-34106 - Cobra+ Sideplanes

| USM Package      | USM_ONESTOR_V5.2_R2019.20.16 |
|------------------|------------------------------|
| Bootloader       | 1.0b                         |
| Firmware         | 5.2.0.207                    |
| Flash Config     | 0x79699f42                   |
| VPD Structure    | 0x01                         |
| VPD CRC          | 0x8f76a88c                   |
| Baseplane Common |                              |
| CPLD             | 0x0e.00                      |
| Baseplane Slot 0 |                              |
| VPD Structure    | 0x01                         |
| VPD CRC          | 0xfb66b9bc                   |

| Baseplane Slot 1 |            |
|------------------|------------|
| VPD Structure    | 0x01       |
| VPD CRC          | 0x022f3609 |

### 2.3.4 SP-34106 - Battleship Sideplanes

| USM Package      | USM_ONESTOR_V5.2_R2019.20.16 |
|------------------|------------------------------|
| Bootloader       | 1.0b                         |
| Firmware         | 5.2.0.207                    |
| Flash Config     | 0x0d5a08e1                   |
| VPD Structure    | 0x1.0                        |
| VPD CRC          | 0xe83c1dc5                   |
| Baseplane Common |                              |
| CPLD             | 0x0e.00                      |
| Baseplane Slot 0 |                              |
| VPD Structure    | 0x2.0                        |
| VPD CRC          | 0xeb90e728                   |
| Baseplane Slot 1 |                              |
| VPD Structure    | 0x2.0                        |
| VPD CRC          | 0x12d9689d                   |

## 2.4 Midplanes - OneStor

### 2.4.1 HB1235

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x15                         |
| VPD Structure | 0x13                         |
| VPD CRC       | 0xb45a58bd                   |

### 2.4.2 EB2425

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x15                         |
| VPD Structure | 0x13                         |
| VPD CRC       | 0x47c74328                   |

### 2.4.3 HB2435

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x15                         |
| VPD Structure | 0x13                         |
| VPD CRC       | 0x9a600a82                   |

### 2.4.4 SP3212A

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x15                         |
| VPD Structure | 0x13                         |
| VPD CRC       | 0x54b4752d                   |

### 2.4.5 SP3212A - Lattice

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x21                         |
| VPD Structure | 0x0x13                       |
| VPD CRC       | 0x18c2c221                   |

### 2.4.6 SP3224A

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x15                         |
| VPD Structure | 0x13                         |
| VPD CRC       | 0xa1796e3d                   |

#### 2.4.7 SP3224A - Lattice

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x21                         |
| VPD Structure | 0x0x13                       |
| VPD CRC       | 0x5f4ab797                   |

#### 2.4.8 SP3584 - Titan 12G

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x03                         |
| VPD Structure | 0x13                         |
| VPD CRC       | 0x746d7800                   |

#### 2.4.9 SP3584 - Titan 12G - Lattice

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| CPLD          | 0x20                         |
| VPD Structure | 0x0x13                       |
| VPD CRC       | 0xaa7722d1                   |

#### 2.4.10 SP34106 - Cobra+

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| VPD Structure | 0x01                         |
| VPD CRC       | 0x08522f1d                   |

#### 2.4.11 SP34106 - Battleship

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| VPD Structure | 0x1.0                        |
| VPD CRC       | 0xe40aca6                    |

### 2.5 Midplanes - OneStor-XP

#### 2.5.1 XP-PL24P

| USM Package        | USM_ONESTOR_V5.2_R2019.20.16 |
|--------------------|------------------------------|
| CPLD               | 0x02                         |
| VPD Structure      | 0x0x10                       |
| VPD CRC            | 0x6c82a1a8                   |
| Ops Panel Firmware | 0x1.3                        |

## 2.6 PCMs / PSUs

### 2.6.1 HE580W Gen2 - OneStor

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x3.3d                       |
| DSP Firmware  | 0x3.0a                       |
| VPD Version   | 0x05                         |
| VPD CRC       | 0x3cfce593                   |

### 2.6.2 HE764W - OneStor

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x2.01                       |
| DSP Firmware  | 0x1.07                       |
| VPD Version   | 0x05                         |
| VPD CRC       | 0xb672a592                   |

### 2.6.3 HE764WDC - OneStor

| USM Package   | USM_ONESTOR_V5.1_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x1.05                       |
| DSP Firmware  | 0x1.03                       |
| DSP2 Firmware | 0x3.03                       |
| VPD Version   | 0x06                         |
| VPD CRC       | 0x2e004680                   |

### 2.6.4 HE764W\_VERC - OneStor

| USM Package   | USM_ONESTOR_V5.1_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x3.00                       |
| DSP Firmware  | 0x1.07                       |
| VPD Version   | 0x05                         |
| VPD CRC       | 0x81201d04                   |

### 2.6.5 HE764WDC\_VERC - OneStor

| USM Package   | USM_ONESTOR_V5.1_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x2.00                       |
| DSP Firmware  | 0x1.03                       |
| DSP2 Firmware | 0x3.03                       |
| VPD Version   | 0x06                         |
| VPD CRC       | 0x2e004680                   |

### 2.6.6 PT580W - OneStor

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x3.03                       |
| DSP Firmware  | 0x2.02                       |
| VPD Version   | 0x05                         |
| VPD CRC       | 0x4d503dd4                   |

### 2.6.7 PT764W - OneStor

| USM Package   | USM_ONESTOR_V5.1_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x2.03                       |
| DSP Firmware  | 0x1.02                       |
| VPD Version   | 0x05                         |
| VPD CRC       | 0xf08cc543                   |

### 2.6.8 TT2200W - SP3584

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x3.09                       |
| DSP Firmware  | 0x0.0f                       |
| VPD Version   | 0x05                         |
| VPD CRC       | 0x79bd5926                   |

### 2.6.9 2200W - SP3584

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x3.06                       |
| DSP Firmware  | 0x3.03                       |
| VPD Version   | 0x05                         |
| VPD CRC       | 0x8d93fe80                   |

### 2.6.10 1440W - OneStor-XP

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x2.12                       |
| DSP Firmware  | 0x2.08                       |
| VPD Version   | 0x0x05                       |
| VPD CRC       | 0x306646c8                   |

### 2.6.11 2000W - SP34106

| USM Package   | USM_ONESTOR_V5.2_R2019.20.16 |
|---------------|------------------------------|
| Main Firmware | 0x1.06                       |

## 2.7 Fan Modules

### 2.7.1 SP3584

| USM Package | USM_ONESTOR_V5.2_R2019.20.16 |
|-------------|------------------------------|
| Firmware    | 01.10                        |
| VPD Version | 5                            |
| VPD CRC     | 0x636b4986                   |

### 2.7.2 XP-PL24P

| USM Package | USM_ONESTOR_V5.2_R2019.20.16 |
|-------------|------------------------------|
| Firmware    | 00.20                        |
| VPD Version | 0x05                         |
| VPD CRC     | 0x533a28fd                   |

## 3 Firmware Update Procedure

### 3.1 OneStor

The following section defines the process for upgrading the OneStor subsystem FW components.

#### 3.1.1 Enclosure Upgrade Steps

The GEM subsystem refers to the following enclosure components:

1. Canister GEM Firmware: Bootloader and main GEM image.
2. Canister flash config and VPD.
3. Canister GEM CPLD and Power CPLD.
4. Midplane VPD and CPLD.
5. PCM/PSU Firmware and VPDs.

SES Page 0Eh is the firmware download mechanism used to upgrade the GEM subsystem. The details for this are covered in the GEM 5.0 ANSI SES Specification and the T-10 ANSI SCSI Enclosure Services - 3(SES-3) documentation.

##### 3.1.1.1 Canister Upgrade

- 1 Using a page 0Eh upgrade utility, download the appropriate combined canister update GFF for the canister.  
GEM will automatically reboot to activate the firmware once the update is complete.
- 2 Repeat step 1 for canister B.

##### 3.1.1.2 Enclosure Upgrade

- 1 Using a page 0Eh upgrade utility, download the appropriate midplane VPD update GFF.
- 2 Using a page 0Eh upgrade utility, download the midplane CPLD update GFF.
- 3 Simultaneously reboot both canister A and B.

##### 3.1.1.3 PCM/PSU Upgrade

- 1 Using a page 0Eh upgrade utility, download the appropriate VPD file for the installed PCM/PSU.
- 2 Using a page 0Eh upgrade utility, download the appropriate individual firmware files for the installed PCM/PSU.

### 3.2 Cobra+ Update Procedure

Follow the steps below to upgrade a Cobra+ enclosure to the firmware levels described in this USM. These steps assume the enclosure is at the R2017.33.0 USM package level including unique WWNs programmed for all expanders.

1. Using a page 0Eh upgrade utility, download the midplane VPD to either IOM controller primary expander.
2. Using a page 0Eh upgrade utility, download the appropriate primary expander combined image. This combined image contains the bootloader, GEM, MAG FPGA and the flash config images.
  - a. Upgrade both IOM primary expanders before moving on to the next step.
3. Using a page 0Eh upgrade utility, download the appropriate secondary expander combined image (the filename will contain “inband”). The combined image contains the bootloader, GEMLite, flash config and VPD.
  - a. Upgrade both secondary expanders before moving on to the next step.
4. Using a page 0Eh upgrade utility, download the appropriate sideplane expander combined image (the filename will contain “inband”) to all of the sideplane expanders. The combined image contains the bootloader, GEMLite, flash config, sideplane VPD, baseplane VPDs and baseplane CPLD.

**Note:** The sideplane combined image will only update the sideplane expanders that are in the same SAS domain as the primary expander. Therefore, the same procedure needs to be completed on the other IOM controller to complete the sideplane updates.

**Note:** The baseplane CPLD is only updated through the primary data sideplane expanders.

5. Using a page 0Eh upgrade utility, download the combined PSU FW file to either IOM controller primary expander.

### 3.3 OneStor-XP

The SUU application and documentation are included in Tools Package 5.8. The firmware must be updated in the order that the component headings are presented below.

#### 3.3.1 BMC

Download and activate the BMC image using the following commands and wait for each to complete. Configurations will be preserved by default. Append ‘-sc “flash(conf)”’ to forcefully overwrite configurations

1. suu --transfer -d <device\_address> -f <filename>
2. suu --select -d <device\_address> -t BMC
3. suu --perform -d <device\_address>
4. The BMC will reboot on activation, this takes roughly 240 seconds to complete
5. Verify the BMC version information with suu --query -fw-v -d <device\_address> -t BMC

#### 3.3.2 CPLD

Download and activate the CPLD image using the following commands and wait for each to complete.

**Note:** CPLD activations in a HA enclosure must be performed on a single canister at a time.

1. suu --transfer -d <device\_address> -f <filename>
2. suu --select -d <device\_address> -t CPLD
3. suu --perform -d <device\_address>
4. The Controller will reboot on activation, this takes roughly 300 seconds to complete
5. Verify the CPLD version information with suu --query -fw-v -d <device\_address> -t CPLD

#### 3.3.3 GEM Components

When updating GEM components using SUU, the operation can only be performed from a single canister in an enclosure at any one time. E.g. while a GEM component is being activated from the canister in slot 0, any attempt to activate a GEM component from the canister in slot 1 will be rejected.

All GEM components can be updated in the following manner:

1. suu --transfer -d <device\_address> -f <filename>
2. suu --select -d <device\_address> -t GEM
3. suu --perform -d <device\_address>
4. If a synchronous GEM reset is required, append ‘-sc “syncgem”’ to the command line for --perform (a synchronous reset of GEM may take up to 30 seconds to complete)

##### 3.3.3.1 Canister Firmware

Update the firmware for the GEM components resident in the canister with the commands shown in 3.3.3 (this will only update the canister firmware on the controller it is executed on).

##### 3.3.3.2 Disruptive Canister Firmware

Firmware components in this update will disrupt I/O. Care must be taken when updating. The files are contained within the disruptive folder. A power cycle may be required as some components (e.g. the SAS controller) will have been restarted.

### **3.3.3.3 Enclosure Firmware**

Update the firmware for the GEM components resident in the enclosure with the commands shown in 3.3.3. This only needs to be performed from one canister in an enclosure.

### **3.3.3.4 Power Firmware**

Update the firmware for the GEM components resident in the power and cooling modules with the commands shown in 3.3.3. This only needs to be performed from one canister in an enclosure.

### **3.3.3.5 Verify GEM Firmware Versions**

Verify the GEM version information with suu --query -fw-v -d <device\_address> -t GEM.

## 4 Change History

This section documents the changes made since the previous USM release.

### 4.1 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.16

| Issue ID  | Description  | Product   |
|-----------|--|-----------|
| FMW-69109 | G280- 5U84 Eco PSU Fault Status, 2.2K PSU firmware 3.09                            | Titan 12G |
| FMW-67372 | Mfg bin files not getting created for sideplanes in the latest releases of G280MR4 | Titan 12G |
| FMW-68698 | Mfg gff config files not getting created for newly added lattice no_remap configs  | Titan 12G |
| FMW-68701 | mfg VPD .gff files have CRCs of older VPDs   | Titan 12G |

## 4.2 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.15

| Issue ID  | Description  | Product                   |
|-----------|--|---------------------------|
| FMW-63095 | G280: Support for 764W PCM and enabling Customer FRU information on 764 PCM(AC-Gold, AC-Plat, DC)  | E12EBD                    |
| FMW-63078 | Physical PHY mapping cannot be enabled with changes to USM physical PHY map enabling config files  | Titan 12G                 |
| FMW-62108 | G280 (GEM 5.2)- JBOD for GEM CLI "reset_saved_zone_info" causes GEM firmware Crash   | All                       |
| FMW-64513 | Part 2: Reduce watchdog refresh interval to 250 ms for SP CPLD v22   | Titan 12G                 |
| FMW-66039 | Update atag for canister flash config flipflop file  | All                       |
| FMW-66034 | Add Lattice config files in 93-1024 & 93-1025 sideplane combined files as part of manifest file  | Jenkins Build Environment |
| FMW-62427 | VPD Product ID missing in Zone Table   | All                       |
| FMW-66470 | Failure in the update of sideplane using SESDownload   | Titan 12G                 |
| FMW-66315 | G280 JBOD-764W DC : UUT is failing at "PSU 1 VPD Update" stage and PCM vpd file is failing to update with sesdownload.                           | All                       |
| FMW-66618 | G280 JBOD : While performing normal/flipflop update with mixed IOM (Lattice + Intel) UUT failed at "PSU 1 VPD Update" stage on 764W AC Gold PSU. | All                       |
| FMW-66952 | G280_MR4_USM20.15 : Combined files are flashing incorrect inband_vpd versions on Sideplanes  | All                       |
| FMW-66971 | G280MR4 JBOD: FF failed for PT764 AC PSU with slot mismatch error with manifest file   | All                       |
| FMW-66914 | G280 JBOD-764W DC : he764wdc_verC PSU FlipFlop file version mismatch.  | All                       |
| FMW-50518 | Unassigned Part Number for Lenovo Titan sidplane FW files  | All                       |
| FMW-67138 | UUT: Items indicated as mismatches even though they matched during testing of No_logical_phy_remap   | All                       |
| FMW-66765 | G280- Cray (SFC 12199166): Issue running UUT exes when FIPs is enabled in the OS   | All                       |
| FMW-65770 | Improve GEM bootloader robustness & add signature bytes to .bin in G280  | All                       |

#### 4.3 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.14

| Issue ID  | Description  | Product           |
|-----------|--|-------------------|
| FMW-62792 | Firmware update failed for Mixed IOM (Lattice and Intel) configuration in flash_manager buffer id update   | E12EBD            |
| FMW-61344 | G280 RBOD CPLD: 5U84 with Macronix Flash sideplane codeload failure  | Titan 12G         |
| FMW-60952 | Add Part No for the Lenovo d3284 version inband sideplane combined files   | Jenkins           |
| FMW-60646 | Need to sync G280 capabilities with GEM 5.2  | E12EBD/ Titan 12G |
| FMW-59108 | UUT [G280 JBOD]: Failure to update to GEM Canister firmware due to flash_manager IO_TIMEOUT  | E12EBD            |
| FMW-58669 | UUT update on 5U is changing drive PHY mappings  | E12EBD            |
| FMW-51425 | QUANTUM   GT280R006-02   5.2.0.95   Unexpected HW power state or mismatch between EBOD and Midplane CPLD power states for drive resulted in a DU situation | E12EBD            |
| FMW-64208 | G280: Revert the sideplane CPLD version from 0x25 to 0x22  | Titan 12G         |

#### 4.4 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.12

| Issue ID  | Description   | Product          |
|-----------|---|------------------|
| FMW-58674 | G280: CPLD type detection at SoD  | E12EBD/Titan 12G |
| FMW-58679 | G280: Lattice Sideplane CPLD inband gff image download getting timeout                | E12EBD/Titan 12G |
| FMW-57667 | G280 JBOD: On Lattice IOM Canister FW is not getting updated through combined file    | E12EBD           |
| FMW-56394 | G280: Jenkins build changes required for supporting Lattice CPLD                      | Titan 12G        |
| FMW-53859 | G280: Code changes for Lattice CPLD update support for midplane, sideplanes and IOM's | E12EBD/Titan 12G |
| FMW-59501 | G280: 5U JBOD: 5U84 ECO PSU Multiple PNs in Manifest                                  | Jenkins          |

#### 4.5 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.11

| Issue ID  | Description   | Product |
|-----------|---|---------|
| FMW-57444 | G280: Add new PCM Firmware files for ECO PCM PT 580W 3.03 main firmware | E12EBD  |

|                         |   |                   |
|-------------------------|---|-------------------|
|                         |   |                   |
|                         |   |                   |
| FMW-53304               | PSU Eco design :2.2KW Unable to Brand or update VPD   | Titan 12G         |
| FMW-54135               | Add capability for default/min zone mode  | All               |
| FMW-53382               | Fix for redundant BROADCAST(SES) due to power manager module and new CLI command to enable BROADCAST(SES) events filter mode. | 2U12              |
| FMW-47035               | G280 fix to avoid EMP communication fault alerts in case of GEM expander reboot   | All               |
| FMW-53687               | Classification of Power Manager SES Broadcasts  | 2U12              |
| FMW-53839               | G280: PSU failure event is not generating if PSU incompatible alert is present  | All               |
| FMW-53055               | G280:Codeload failure - bootloader version mismatch for Gallium   | E12EBD/Titan 12G  |
| FMW-45797               | G280: Titan 5U84 Support for the Flex Eco Design 2.2KW Titanium PSU   | Titan 12G         |
| FMW-51647               | G280: Titan3/Pimlico - Add Single Bank NOR flash Support (13-1088 Micron Singlebank)  | E12EBOD/Titan 12G |
| FMW-52758               | 'set_fanvpd' command timed out issue  | All               |
| FMW-50342               | G280: codeload with pfu and io fails due to degraded drives   | All               |
| FMW-47121               | Root expander experienced a communication fault   | All               |
| FMW-50518               | Unassigned Part Number for Titan sidplane FW files  | Titan 12G         |
| FMW-43704/<br>FMW-48343 | An alert condition was detected on a sideplane element - Master Case  | Titan 12G         |
| FMW-48142               | Add logical PHY mapping to defaults on Titan sideplanes   | Titan 12G         |
| FMW-46521               | G280: Jenkins changes to Add PT580W files to G280 build   | 2U/4U ENC         |
| FMW-45197               | VPD format version reporting in USM manifest is not consistent  | All               |
| FMW-42238<br>/FMW-45597 | Generating suu and gff binaries from vendor provided raw hex files and pcm_vpd.bat PT580W                                     | 2U/4U ENC         |
| FMW-41534<br>/FMW-36364 | LENOVO: UUT: D3284 fails to upgrade FW - both with BOMC and standalone package  | All               |
| FMW-36364               | G280 Overlapped command Check Condition seen with no overlapped command   | All               |
| FMW-57495               | G280: Add new PCM Firmware files for ECO PCM TT 2.2KW 3.07 main firmware  | Titan 12G         |

## 4.6 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.10

| Issue ID                | Description   | Product           |
|-------------------------|---|-------------------|
| FMW-33990               | Fix GEM CLI 'set_pcmvpd'                                  | All               |
| FMW-43462               | Fix GEM CLI 'ddump_pwrmgr' to show correct PCM/PSU SN     | All               |
| FMW-43225               | Fix EBOD Titan sideplane down issue on EBOD CPLD update   | Titan 12G, E12EBD |
| FMW-42630,<br>FMW-42514 | Coverity fixes  | All               |
| FMW-44331               | Fix for Swap bit of Host Temp. sensor not getting cleared | Gal3              |
| FMW-44959               | PMC 12G Treck TCPIP Stack Patch for Ripple 20             | E12EBD            |
| FMW-42096               | Suppress same repeated SES PAGE 2 Ctrl requests           | All               |

## 4.7 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.9

| Issue ID  | Description   | Product  |
|-----------|---|----------|
| FMW-42109 | Added zone modes to RSS sideplane config as well, to be used in channel customers as well | Titan12G |
| FMW-42120 | Drives taking long time (approx 150 sec) to detect after SP combined file flash           | Titan12G |
| FMW-41430 | New Zone Mode Support(2 Drive Group) on generic Titan12G configuration                    | Titan12G |

## 4.8 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.8

| Issue ID  | Description   | Product  |
|-----------|---|----------|
| FMW-40715 | SATA Drive and Zoning Support on generic Titan12G configuration | Titan12G |

## 4.9 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.7

| Issue ID  | Description  | Product  |
|-----------|--|----------|
| FMW-35299 | High fan speed due to PCM hotspot temperature. Updated target temperature threshold in 2.2 KW PSU VPD. | Titan12G |

## 4.10 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.6

| Issue ID                | Description  | Product       |
|-------------------------|--|---------------|
| FMW-33752               | TT-51976-Intermittent Fan Failure and Recovery                   | Titan12G      |
| FMW-35158               | Root Expander Comms Failure                                      | 2U/4U ENC     |
| FMW-29997               | Midplane vpd corruption  | Gal3 + 2U ENC |
| FMW-35131               | Update Midplane CPLD Low density to v15                          | 2U/4U ENC     |
| FMW-36736               | Ported Flash manager fixes from GEM 5.3 branch                   | All           |
| FMW-34503/<br>FMW-35348 | GEM reports PCM Voltage and Current sensor values 0 after reseat | All           |
| FMW-36365               | Cable LED remains ON even on cable removal                       | All           |
| FMW-32255               | Recovery Mode causes lost enclosure, vdisks in QTOF              | Titan12G      |

## 4.11 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.5

| Issue ID  | Description  | Product   |
|-----------|--|-----------|
| FMW-33992 | G280 Ambient temperature sensor inaccurate on 2U12/2U24/4U24   | 2U/4U ENC |
| FMW-31339 | TITAN: 2.2kW PCM: Updated warning and critical Temp Thresholds | Titan 12G |

## 4.12 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.4

| Issue ID  | Description  | Product   |
|-----------|--|-----------|
| FMW-26007 | Software watchdog GEM after stack overflow(set_enc_id failed)        | E12EBD    |
| FMW-31908 | GEM crash on CLI 'hspower'   | Titan 12G |
| FMW-31089 | Stack overflow when serial port is in use, trigger IO module reboot. | E12EBD    |

## 4.13 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.3

| Issue ID  | Description  | Product |
|-----------|--|---------|
| FMW-30004 | PSU Update fails with status 7 (UNSUCCESSFUL)                                | All     |
| FMW-30852 | GEM 5.2: Titan: Drive PHY mapping errors                                     | All     |
| FMW-31084 | Stack overflow causing Telnet server reset and IO module reboot - Workaround | E12EBD  |
| FMW-31055 | Updated E12EBD canister CPLD to v0x0B  | E12EBD  |

## 4.14 Issues addressed in USM\_ONESTOR\_V5.2\_R2019.20.2

| Issue ID  | Description   | Product   |
|-----------|---|-----------|
| FMW-29370 | Side plane removal of cover leads to both sideplanes failing, not just the one being serviced | All       |
| FMW-29129 | GT275R005-04   Power supply status stays Amber! (TT51212)                                     | All       |
| FMW-30272 | Change Bootloader version reporting format for sideplane                                      | Titan 12G |
| FMW-29594 | Need some changes in xml file of Customer combined package                                    | Jenkins   |
| FMW-27413 | Remote connection fault Reported - cable Fault LED ON   | Titan 12G |
| FMW-26006 | jbod_conf help for set_zone_mode missing optional parameter                                   | All       |
| FMW-24634 | Cannot see all drives after 5U84 or 3284 are power cycled when connected to 930-8e HBA        | All       |

|                    |   |       |
|--------------------|---|-------|
| FMW-24245          | GEM 'driveinv' command does not list the drive temp   | All   |
| FMW-24194          | Re-inserted SAS cable takes ~9 min for I/O to failback in RHEL 7.3 & ServerRAID M5225 HBA                 | All   |
| FMW-21270          | Incorrect drive temperature reported by driveinv  | All   |
| FMW-22648          | VMware ESXi 6.5 drives Unconfigured Bad if 5U84 enclosure is powered on after server                      | All   |
| FMW-22649          | RAID arrays not shown by MegaRAID Storage Manager with VMware 6.5, GUI also freezes                       | All   |
| FMW-23450          | jbodupdate.x86_64_rhel6 hangs up after sideplane USM download on 5U84 in a mixed config                   | All   |
| FMW-22275          | Member drives disappear from 5U84 md RAID arrays causing I/O failures whenSAS cable pulled and reinserted | All   |
| CSIT-66            | LSI Storage Authority (LSA) 3.023.000.000 only sees 237 of the 260 drives present                         | All   |
| CSIT-72 / BCOM-352 | Incorrect number of drives detected in D3284 with Vero  | All   |
| FMW-26241          | SAS cables pulled resulting in Sled 0 & 1 fault: Phy connection failure on 5U84ENC                        | All   |
| FMW-24991          | Storage 2U12/2U24 Assertion Crash after AC Power Loss event   | 2U    |
| FMW-25157          | 2U24 for SAPHANA encounters hardreset resulting in DU condition   | 2U24  |
| FMW-26324          | Jbodupdate v5.1 - 'Firmware Activation Failed - Status: 256' with RAID 930-8e and 5U84ENC                 | Titan |
| FMW-26195          | Jbodupdate -- Error - Enclosure Rediscover Time Out on a 5U84ENC Variant                                  | Titan |
| FMW-24622          | jbodupdate r failed toupdate enclosure when usingasingle SAS cable connected to930-8e                     | JBOD  |
| CSIT-182           | Drive disappeared on a RHEL 7.6 server after a SAS cable pull   | All   |
| FMW-29016          | Jbodupdate summary should not list non-Seagate enclosu <del>s</del> asgate Internal                       | All   |
| FMW-28866          | ADAPT pool in QTOF the other in FTDN - TT51127  | All   |